

TERMS OF REFERENCE

Repair of PHILGUARANTEE Service Vehicle: 2009 Mitsubishi Montero, A/T, and diesel with plate number ZTV 300

I. SCOPE OF WORK

- Labor: Engine Code Trouble: P0106, Baro Manifold absolute Pressure Sensor U1102, U1102; ELC-AT CVT; P177 / Overhaul AT; Replace input/output sensor, Reprogram ECU: ABS Rear Wheel Speed Sensor, Replacement of Parts, Clutch Fan cleaning, Brakes, Bulb;
- b) Provide the following: Overhauling kit (1pc), Rear wheel speed sensor (1lot), Airbag BI 476; B1551 and Spiral Cable (1lot), Plate light bulb (1pc), Brake shoe (1set), Brake pad (1set), Silicon oil for clutch fan (6pcs);
- Provide the required parts and supplies for the above Scope of Works.
- II. TERMS OF DELIVERY: 15 calendar days upon receipt of Job Order. (Delivery of repaired vehicle should be on business days only)
- III. TERMS OF PAYMENT: 30 calendar days from receipt of billing.
- IV. APPROVED BUDGET FOR THE CONTRACT (ABC):

The Approved Budget for the Contract is **Sixty-Five Thousand Seven Hundred Pesos only (₱65,700.00),** inclusive of all applicable taxes, chargeable against the Corporate Operating Budget for CY 2022.

Prepared by:

EARL TIMOTHY C. MOJICA

Procurement Officer II

Reviewed by:

MARWYN ANTHONY C. GALANC

Administrative Officer V

Approved by:

ROSEMARIE N. PRINCIPE

Vice President

Facilities and General Services Department